

No. - 1570

Date -> 25/07/2023

## BUILDING SEFTY CERTIFICATE

Visited the school building belong to CARMEL SCHOOL KARELI ,  
Barman Road , Kodsas Narsinghpur (M.P.) and noted following contents :-


1. Structural components as beams , columns are in good and proper sizes
2. Finishes material used as weather proof, rust proof etc.
3. Overall structure sounds good and strong to bear to its load, and safe against live loads also.

So I recommend building in safe in all respects.

Place: Narsinghpur

Date:- 25/07/2023

  
उपयत्री  
नगर पालिका परिषद करेली

  
मुख्य नगर पालिका अधिकारी  
नगरपालिका परिषद, करेली